

List of Machinery & Plant at Fymawr West  
Quarry

Saw Mill:-

- 2 Saw Tables (Two pulleys missing)
- 1 Length of Shafting, about 15 ft by  $3\frac{1}{2}$  inch.
- 1 Large Pulley on shafting
- 1 Small do " "
- 4 Pulleys on the floor.
- 2 Rubbish Waggon
- 1 Trolley.
- 1 Barrow
- 1 do. (Car Carriage)
- 8 Incline Rollers
- 33 Rubbish Waggon Wheels
- 1 Punching Machine
- 1 Bavel Cogwheel
- 1 Strong Narrow Iron Drum
- 2 Cast Steel Drill Steels
- 1 Pedestal
- 10 Waggon Axles
- 1 Ladder (wood)
- 1 Smoothing Turn Table
- 2 Small Pulleys
- 1 Coil Gal. Wire Rope
- 1 Slate Cistern
- 2 Sieves
- 1 Bench
- 1 Small Table
- About a dozen Waggon Buckets
- 1 Grindstone Stand.
- A quantity of Old Iron.

Quarry Bank:-

A quantity of Slates - (discolored)  
1 Rubbish Waggon  
Few Rails

Office :-

1 Cupboard  
1 Small table

Boiler Room: etc

1 Robey Boilers (In bad order)  
1 Small Stationary Steam Engine  
Driving Saw Mill.  
1 Anvil  
1 Stationary Steam Engine  
1 Drum and Wire Ropes  
1 Belt-driven Air Compressor  
by Ingersoll-Rand

Top Galleries:-

Few tons of Rails  
2 Rubbish Waggons  
4 Damaged Waggon Bodies  
1 Small Drum Centres & Axle  
1 Small Crab-Winch.

Feb. 7. 1937

W. J. Griffin